


Fig 1c *Prior Art*

AMPLITUDE

AMPLITUDE

เลสสมาริกัดสัสก็จะสุดิจ



TIME

AMPLITUDE

Early Zero crossing 310

Correct Zero crossing 320

√300

TIME




Fig. 4

500
Process wareform or sol
—————————————————————————————————————
Measure + ransit time for ultrasonic signals
Measure transit time for ultresonic signals along a first path in meter ~ 510
<u> </u>
Measure transit time for ultrasonic signals - 520 along a second path in meter
Determine whether those exists an
ultrasonic arrival timing from based on
the length of the first path, the length ~530
of the second path, the transit time
for the first path, and the transit time
for the second path or on a speed of sound for a medium in said meter
5Ux
Correct for measurement error

Fig. 5